



Bestaande situatie vanuit de
hal richting kerkzaal



Nieuwe situatie
2 dubbele deuren richting Het
Trefpunt i.v.m. brandvoorschrift

A 3D architectural rendering of a hallway. The walls are made of dark brown brick. The ceiling is made of horizontal wooden slats. On the right side, there is a glass door with a dark red frame and a white border. The door is slightly ajar, revealing a glimpse of the area outside, which has a light-colored floor and a blue mat. The lighting is dim, creating a moody atmosphere.

Bestaande situatie vanuit de
hal richting Het Trefpunt



Nieuwe situatie met
boekentafel



De nieuwe ontvangstruimte vanuit de hal van de kerk richting Het Trefpunt



De nieuwe ontvangstruimte vanuit de
Het Trefpunt richting kerk